# Manufactured Home Appraisal Prepared by Datacomp Appraisal Services

Ordered by Lender Buyer Seller / Owner Retailer	Spartans P	roperties	/ Applicatio	n # MB 3142				
Subject Property	<i>'</i>							
Park	Country Me	eadows		Cou	nty	Wayne		
Address	28714 Map	leleaf Dr		Lot	#			
City	Flat Rock		St	اا <b>Zip</b>		48134		
<b>Community Rating</b>	Good/Exce	llent		Home Con	ditio	<b>n</b> Good -		
Make	Holly Park		Manufacture Year		1990			
Model	Holly Park			<b>Bedrooms</b>		2		
Color	White			Bathrooms	5	1		
Serial Number	01FRR2506	51		<b>HUD Tag</b>		NTA217942		
Size	14 <b>x</b> 68	<b>=</b> 952	Sq. Ft.	Siding Typ	e	Lap		
Additional	x	=	Sq. Ft.	<b>Roofing Ty</b>	рe	Peak Shingled		
Additional	x	=	Sq. Ft.	Total Sq. F	t.	952		
Comments Good condition it wou Meadows are double Country Meadows and used to complete app Comparable #1 was re	<mark>uld have a va</mark> wide. The m d from simila oraisal. Com	alue of \$3 lost recer ar commu parables	<mark>37,400</mark> . App nt and most unities withi bracket sub	roximately 7! similar comp n a 15 mile p ject by year/a	5% of parabl proxim	es available from nity search were		
				Estima	ated			
Sale Price	-			Market V	alue	\$30,600 As Is		
This is a TYPE 2 appraisal and is attached). Since it may have be be relied upon by any other per	en prepared per t							
Appraiser Sig	holward S.	Ballaufi		Date	01/	15/2025		
	Ed Ballance			I.D.	DM	DMI58767303		
Datacomp Appraisal Services	s • 2600 Five Mi	le Road NE, (	Grand Rapids, M 8062	l 49525 • Phone:	(800) 3	865-1415 • Fax: (800) 841-		

© 2025 Datacomp Appraisal Systems, Inc. ®

#### **Home Inventory**

Item

Bathroom 1 Garden Tub, Exhaust Fan, Medicine Cab

Bedroom 1

Bedroom 2 Carpet/Vinyl

Ceiling Fans # 2 Smoke Detectors # 2

Thermopane Windows

Walls

Bay Windows Full

Central Air Conditioner Size: Small, Brand: Standard

Roofing Peak Shingled

Sets of Steps # 2

Shutters

Siding Lap
Skirting Standard

Window Awnings 3'=1; 5'=1; 10'=1

Garbage Disposal

Refrigerator Brand: Frigidaire, Double Door, Frost Free

Stove Brand: Maytag, Standard

Cathedral Ceiling

 $\begin{array}{ll} \text{Deck} & 10 \times 11 \\ \text{Deck} & 09 \times 21 \\ \text{Storage Shed Wood - Unattached} & 08 \times 12 \\ \text{Amps Electric} & 100 \\ \end{array}$ 

Water Heater Size 30 Gallons

Wired / Plumbed for Washer

© 2025 Datacomp Appraisal Systems, Inc. ®

### **Condition Information and Comments**

#### **Poor Fair Good Exc Comments**

	POULL	iir Good	IEXC	Comments
Exterior Items				
Siding Condition		•		Dirty in some areas.
Exterior Items				
Skirting Condition		•		Dented panels, missing panels, misaligned panels.
Window Condition		•		
Exterior Door Condition		•		
Overall Exterior Condition		•		Decks show some wear.
Structures				
Deck Condition	•	•		
Deck Condition		•		
Storage Shed Condition		•		
Entire Exterior				
Air Condition				
Home / Site				
Information				
General Comments				<b>CeilingType</b> : Imperfections visible. <b>Walls</b> : Imperfections visible. Datacomp was unable to locate home's Data Plate.
Living / Dining Room				
Ceiling Condition		•		
Floor Condition		•		
Wall Condition		•		
Kitchen				
Ceiling Condition		•		
Floor Condition		•		
Wall Condition		•		
Cabinet Condition		•		Some wear.
Counter Condition		•		
Bathroom				
Ceiling Condition		•		
Floor Condition		•		
Wall Condition		•		
Cabinet Condition		•		
Tub / Sink Condition		•		

© 2025 Datacomp Appraisal Systems, Inc. ®

#### **Condition Information and Comments**

#### **Poor Fair Good Exc Comments**

<b>Bedroom</b> Ceiling Condition		•	
Floor Condition		•	
Wall Condition		•	
<b>Bedroom</b> Ceiling Condition	•		
Floor Condition	•		Worn, dirty.
Wall Condition	•		Worn.
Entire Interior InteriorDoor Condition		•	
WindowSill Condition		•	
Molding Condition		•	

© 2025 Datacomp Appraisal Systems, Inc. ®

#### **Location Evaluation**

#### **Community**

 Community Name
 Country Meadows

 Community Address
 3211 Will Carleton Road

 Community City, State, Zip
 Flat Rock, MI 48134

 Location Rating
 Good/Excellent

Number of Sites 577
Number of Vacant Sites 18

Number of Rental Homes 121

Adult / Retirement CommunityNoClubhouseYesRecreational FacilitiesNoPoolNoOffstreet ParkingYes

**Community Owner Rights** Fee Simple **Resident Lot Rights** Land Lease

#### **Subject Home**

	Below Average	Average	Above Average
<b>Landscaping of Subject Site</b>	•		
Overall Appearance of Site			•
Location of Home within Community		•	
Number of Homes for Sale in the Immediate Neighborhood	•		
	Older	Same	Newer
Age of Homes in the Immediate Neighborhood		•	
Excavated Site	No		
<b>Home Owner Occupied</b>	No		
Home Visibly for Sale	Yes		
© 2025 Datacomp Appraisal Systems, Inc. ®			MB 3142 DMI58767302





© 2025 Datacomp Appraisal Systems, Inc. ®






© 2025 Datacomp Appraisal Systems, Inc. ®





© 2025 Datacomp Appraisal Systems, Inc. ®





 $\ensuremath{\mathbb{C}}$  2025 Datacomp Appraisal Systems, Inc.  $\ensuremath{\mathbb{R}}$ 





© 2025 Datacomp Appraisal Systems, Inc. ®






 $\ensuremath{\mathbb{C}}$  2025 Datacomp Appraisal Systems, Inc.  $\ensuremath{\mathbb{R}}$ 





© 2025 Datacomp Appraisal Systems, Inc. ®



© 2025 Datacomp Appraisal Systems, Inc. ®

### **Comparable Analysis Worksheet**

	Subject	Comp # 1	Comp # 2	Comp # 3
Make	Holly Park	Clayton	Skyline	Redman
Model	Holly Park	Clayton	Winner	72S3BD
Size 1	14 x 68	14 x 67	14 x 67	15 x 68
Size 2				
Size 3				
Year	1990	2008	1989	1995
SellingPrice		\$26,500	\$35,900	\$37,199
Option Package	\$7,435	\$7,155	\$10,427	\$6,175
Option Package \$		\$218	\$-2,333	\$982
Quality	Standard	Standard	Standard +	Standard
Quality Adjustment			\$-2,513	
Age Difference		-18	1	-5
Age Adjustment		\$-6,625		\$-1,859
Square Feet	952	938	938	1,020
Size Adjustment		\$190	\$250	\$-1,365
Home Condition Rating	Good -	Fair/Good	Good	Good
Condition Adjustment		\$3,180	\$-1,436	\$-1,487
Community Name	Country Meado	Country Meado	Belle Villa Mead	Rawsonville Wo
<b>Community Quality</b>	Good/Excellent	Good/Excellent	Good/Excellent	Good
Community Adjustment				\$1,487
,				
Zip Code	48134	48134	48111	48111
County	Wayne	Wayne	Wayne	Wayne
CPI Adjustment	Wayne	Wayne	Wayne	wayne
Date of Cal		12/02/24	02/10/24	00/17/24
Date of Sale Time Adjustment		12/02/24	03/19/24	09/17/24
Adjusted Market Value		\$23,463		-
Net Adj %		-11%		-6%
Gross Adj %		39%	18%	19%

 Market Value
 \$30,600.00

 Repairs
 \$0.00

 Estimated Market
 \$30,600.00

Value

 $\ensuremath{\mathbb{C}}$  2025 Datacomp Appraisal Systems, Inc.  $\ensuremath{\mathbb{R}}$ 

### **Comparable Analysis Worksheet**

	Subject	Comp	# 4	Comp # 5	Comp	# 6
Make	Holly Park	Patriot		Redman	Skyline	
Model	Holly Park	Patriot		72F2BG	Winner Lii	mited
Size 1	14 x 68	14 x 66		14 x 68	16 x 77	
Size 2						
Size 3						
Year	1990	1996		1990	1998	
SellingPrice			\$29,000	\$31,399	9	\$39,900
Option Package	\$7,435	\$6,458		\$7,872	\$8,336	
Option Package \$			\$762	\$-340		\$-702
Quality	Standard	Standard		Standard	Standard	
Quality Adjustment	Staridard	Standard		Staridard		\$-2,793
Quality Aujustillelit						ψ- <b>∠</b> ,733
Age Difference		-6		0	-8	
Age Adjustment			\$-1,740			\$-3,192
Age Aujustinent			Ψ 2,7 .0			Ψ 3,131
Square Feet	952	924		952	1,232	
Size Adjustment			\$450			\$-4,734
-						
<b>Home Condition Rating</b>	Good -	Good		Good -	Good	
<b>Condition Adjustment</b>			\$-1,160			\$-1,596
Community Name	Country Meado		l Mead		Huron Est	ates
Community Quality	Good/Excellent	Good		Good/Excellent	Good	
			\$1,450			\$1,596
Community Adjustment						
Zip Code	48134	48186		48197	48174	
County	Wayne	Wayne		Washtenaw	Wayne	
CPI Adjustment						
-						
Date of Sale		10/02/24		08/02/24	03/06/24	
Time Adjustment						
Adjusted Market Value			\$28,762	\$31,059	9	\$28,479
Net Adj %			-1%	-1%		-29%
Gross Adj %			19%	1%		37%

 Market Value
 \$30,600.00

 Repairs
 \$0.00

 Estimated Market
 \$30,600.00

Value

 $\ensuremath{\mathbb{C}}$  2025 Datacomp Appraisal Systems, Inc.  $\ensuremath{\mathbb{R}}$ 

#### DEFINITIONS, CONTINGENCIES AND LIMITING CONDITIONS

DEFINITIONS: DATACOMP APPRAISAL SYSTEMS, hereinafter "DAS", offers two types of manufactured home appraisals, each serving the unique needs of our client.

TYPE ONE appraisals start with the "book" value for the home as published in the NADA Manufactured Housing Appraisal Guide, adjusted for the state location. The "book" value is then further adjusted based on an on-site inspection of the home and the community. Since the NADA Manufactured Housing Appraisal Guide value is based on a depreciated replacement cost approach, it may not represent the true current local market value of the home. Depending on the local market conditions the home could have a fair market value substantially lower or higher than this depreciated replacement cost value. This type of appraisal is commonly referred to as an "NADA" appraisal and commonly used by lenders specializing in manufactured home loans. Datacomp does not warrant the accuracy of the values in a TYPE ONE appraisal.

TYPE TWO appraisals are market value appraisals as indicated by what other similar homes have sold for in the subject home's market area. This type of appraisal is commonly referred to as a "Comp" appraisal and also includes an on-site inspection of the home and the community. The comparable sales information is most often obtained 1) from our proprietary database of homes that we've appraised, or 2) from sales information solicited from local community managers, manufactured home dealers, or others in the local area who may have knowledge of specific and recent manufactured home sales. The general lack of MLS or Government records in the manufactured housing industry makes these comparable sales difficult to verify or validate, and therefore Datacomp does not warrant the accuracy of the values in a TYPE TWO appraisal. In the event a client desires verification and validation of comparable sales information sources, special arrangements for additional time and fees can be made to perform such research on a best efforts basis. Unless a Source Data Verification Addendum is attached to this report, this research was neither requested nor performed.

CONTINGENCIES AND LIMITING CONDITIONS: This report is subject to the following conditions and to such other specific and limiting conditions as are set forth in the report.

- 1. DAS assumes no responsibility for matters of a legal nature affecting this property or the title thereto, nor does DAS render any opinion as to the title, which is assumed to be good and marketable. The property is assumed to be under responsible ownership.
- 2. Neither DAS nor any of its representatives is required to give testimony or appear in court because of having made this report, unless arrangements therefore were made at the time this report was ordered.
- 3. DAS assumes that there are no hidden or unapparent conditions of the property which would render it more or less valuable. DAS assumes no responsibility for such conditions, or for engineering which might be required to discover such factors. No engineering tests were requested or made in conjunction with this report and no responsibility is assumed for the soundness of the structure.
- 4. Information, estimates, and opinions furnished to DAS, and contained in the report, including but not limited to information regarding whether this home is in a Special Flood Hazard Area (SFHA) were obtained from sources considered reliable. DAS does not guarantee the accuracy of this information.
- 5. DAS uses Independent Contractors to perform some functions of the appraisal process.
- 6. Disclosure of the contents of this report is governed by the Bylaws and Regulations of the professional organizations with which DAS is affiliated.
- 7. On all reports that are subject to completion of repairs, or alterations of the home, the report and value conclusions, if any, are contingent upon completion of the improvements in a workmanlike manner.
- 8. DAS assumes that the home and its component parts, including but not limited to appliances, tie-down systems, heat tape installations, heating and cooling systems, electrical systems, and plumbing systems were installed or will be installed in compliance with all local building codes and does not warrant the adequacy of any such installation.
- 9. DAS assumes, without testing, that all components and appliances are in safe working order unless noted otherwise.
- 10. DAS assumes that the owner is in peaceful possession of the property in question and is not unduly restricted from transferring the right of occupancy of the premises on which the home is located unless so noted in the report.
- 11. In the event the owner of the land on which the subject home is located requires certain improvements to the subject home upon resale, DAS assumes no responsibility for identifying such required improvements. Unless specifically stated to the contrary, the estimate of value, if any, includes only those improvements that have been made at the time the home was inspected for purposes of this report.
- 12. DAS will utilize its best efforts to determine the year of manufacture, manufacturer and model, but does not warrant the accuracy of this information.
- 13. DAS will utilize its best efforts to determine the existence of axles but does not warrant the accuracy of this information or the adequacy of the axles to transport the home.
- 14. DAS will utilize its best efforts to determine the existence of a tie down system but does not warrant the accuracy of this information or the adequacy of the system.
- 15. DAS does not warrant the market value, if any, or cost approach value, if any, nor does it warrant the marketability of the home at that value. Comparable sales data, if used, is gathered from sources including, but not limited to, our past appraisal data, manufactured home dealers, and community managers. DAS does not guarantee the correctness of their information nor does DAS verify or validate such information unless a Source Data Verification Addendum has been attached to the report.
- 16. DAS assumes that the property is being used in compliance with all applicable zoning and use regulations and with all Federal, State and local ordinances, including environmental regulations.
- 17. No environmental impact studies were requested or made in conjunction with this report. It is assumed, unless otherwise stated in this report, that the property is not affected by environmental problems either on site or in close proximity.
- 18. No air quality analysis were requested or made in conjunction with this report. It is assumed, unless otherwise stated in this report, that the property is not affected by air quality problems resulting from formaldehyde, radon gas or any other substance.
- 19. This report is furnished solely for the benefit of the person or entity first invoiced for this report. However, in no event shall DAS be liable for any incidental, consequential or special damages. This report may not be used or relied upon by any other person or entity without our prior written consent and payment of a fee. No person or entity shall be deemed to be a "third party beneficiary," or otherwise entitled to rely on this report unless specifically identified in writing as a "third party beneficiary".
- 20. An Appraisal or Home Inspection completed by Datacomp is not meant to replace a Structural Home Inspection to determine the structural integrity of the home and related systems.

© 2025 Datacomp Appraisal Systems, Inc. ®

12119 DMI587673